

VEHICLE INSPECTION REPORT

DK67VVR

Man TGM 18.250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Livingston

GVW 18000kg

Cab Type DAY CAB

Reg. date 27/12/2017

Colour BLUE

Gearbox AUTOMATIC

Year 2017

VIN WMAN08ZZ7JY368283

Axle Combi 4x2

Mileage 200,311 Km Warranted

Body Style Dropside & Crane

Rear Suspension Steel

Fuel Type DIESEL

MOT Due 31/03/2027

HMF 1420K REMOTE CRANE (YEAR 2017), REAR VIEW CAMERA, SURROUND CAMERA SYSTEM.

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4



OSO1 OSO2 OSO3 OSO4

Features


- Radio/CD

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



3: Wing osf
Rusted
Over 5mm



4: Wing nsf
Chipped
Multiple Chips



5: Door nsf
Dented
With Paint Damage

6: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK