

VEHICLE INSPECTION REPORT

P700MKM

Iveco Eurocargo STRALIS 360

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply
		Cap Code	999900

Details

Location	Doncaster	Colour	YELLOW	Gearbox	AUTOMATIC
Reg. date	03/07/2019	VIN	WJME62RN40C406163	Axle Combi	6x2
Year	2019	Body Style	Curtainside	Rear Suspension	Steel
Mileage	206,439 Km Warranted	Service history	None	Rear Doors	Barn
Fuel Type	DIESEL	MOT Due	30/09/2027		
GVW	26000kg	Cab Type	DAY CAB		

NO ACCESS TO REAR C/W LOADMAC 825 FORKLIFT TRUCK (YEAR 2019), VIN: 825-470 *HYDRAULIC LEAK FROM MAST*


Tyres






NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Digital radio


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
Rusted



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Qtr Panel Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



4: Door osf
Chipped
Edge Chip



5: Moulding nsf Wing
Broken
Replace



6: Bumper Front
Scratched
Rusted

Interior

Carpet Condition -
Seat Condition -

Upholstery Condition -
Odour -

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK

