

VEHICLE INSPECTION REPORT

HN16USW

Iveco Daily 70-170

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Present
		Cap Code	999900

Details

Location	Livingston	Fuel Type	Diesel	Body Style	Tilt & Slide
Reg. date	14/05/2016	GVW	7000kg	Gearbox	MANUAL
Year	2016	Colour	WHITE	Axle Combi	4x2
Mileage	505,483 Km Not Warranted	VIN	ZCFC170C905092606	Rear Suspension	Steel

NON-RUNNER TURNS OVER DOES NOT START, ENGINE PARTS STRIPPED J & J TILT AND SLIDE, S PRO WINCH.

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD

Photos





Condition Check



Damage Photos



1: Bumper Front
Chipped
Multiple Chips

2: Bonnet
Chipped
Multiple Chips



3: Door osf
Dented
Over 30mm

4: Panel Front
Rusted
Over 5mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs		Fault		Gearbox 1st and Reverse Test		Fault	
Brakes		Fault		Clutch Slip Test from Static		Fault	
Turbo Boosting		Fault		Gearbox Static Gear Selection (engine running)		Fault	
Parking Brake		Fault		No Excessive Smoking		Fault	
EML light illuminated		Fault		Oil warning light illuminated		Fault	
Airbag light illuminated		Fault		DPF light illuminated		Fault	
ABS light illuminated		Fault		Service indicator light illuminated		Fault	
Windows		OK		Radio		OK	
				Steering		Fault	