

VEHICLE INSPECTION REPORT

C322174

DENNISON SKELETAL FIXED

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Bedford	Fuel Type		Axle Combi	Tri
Reg. date	01/01/2011	Colour	RED	Rear Suspension	Air
Year	2011	VIN	26747		
Mileage	Not Showing	Body Style	Trailer		

BPW AXLES, TWIST LOCKS (8), RAISE & LOWER VALVE

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



