

VEHICLE INSPECTION REPORT

BHA757Y

SEDDON R17 N13

Inspection

Vehicle

VAT	Margin
V5	Buyer To Apply
Cap Code	999900

Details

Location	Onsite Customer Auction	Fuel Type	Diesel	Cab Type	DAY CAB
Reg. date	01/01/1983	Colour	GREEN/RED	Gearbox	Manual
Year	1983	VIN	75117	Axle Combi	4x2
Mileage	95,872 Miles Not Warranted	Body Style	Flatbed		

Requires New Battery & Steering Lock

Tyres

NSF
NSR
OSF
OSR
Spare