

VEHICLE INSPECTION REPORT

LO20VSN

Ford Ranger Raptor 2.0 EcoBlue 213

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	Buyer To Apply
		Cap Id	44068
		Cap Code	FORA20RAP 7DTA4 6 L

Details

Location	Livingston	GVW	3130kg	CAP Average	£16,650.00
Reg. date	22/06/2020	Colour	GREY	CAP Below	£13,350.00
Year	2020	VIN	6FPPXXMJ2PKS27612	Gearbox	AUTOMATIC
Mileage	Not Showing	Body Style	Pickup Double Cab	Gears	1
Fuel Type	Diesel	CAP Clean	£19,000.00		

NON-RUNNER, DOES NOT START OR DRIVE, ENGINE IN REAR, NO KEYS MOT HISTORY SHOWS LAST KNOWING MILEAGE 71,875 MILES ON 28/11/2024, TOW BAR, E/MIRRORS, LEATHER, REAR VIEW CAMERA, HEATED WINDSCREEN.

Tyres


NSF
NSR
OSF
OSR
Spare

Features


- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Door Moulding osf
Broken
Replace



2: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



3: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint

4: Boot Lid
 Cracked
 Replace



5: Other
 N/A
 N/A

6: Bonnet
 Missing
 Replace

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	Fault	Gearbox 1st and Reverse Test	Fault
Brakes	Fault	Clutch Slip Test from Static	Fault
Turbo Boosting	Fault	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	Fault	No Excessive Smoking	Fault
Airbag light illuminated	Fault	Oil warning light illuminated	Fault
ABS light illuminated	Fault	DPF light illuminated	Fault
		Service indicator light illuminated	Fault