

## VEHICLE INSPECTION REPORT

**YO19OUN**

### Ford Transit Connect 1.5 EcoBlue 100ps

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT  
V5 Buyer To Apply

#### Details

Reg. date	07/05/2019	VIN	WF0SXXWPGSKD62094	CAP Average	£3,950.00
Year	2019	Body Style	Panel Van LWB	CAP Below	£3,150.00
Mileage	110,964 Miles Warranted	Keys	1	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	Expired	Gears	6
Colour	WHITE	CAP Clean	£4,500.00	Doors	2

\*NON-RUNNER TURNS OVER DOESN'T START\*

#### Tyres

NSF

NSR

OSF

OSR

Spare

### Features

- Radio/CD
- Cloth seat trim
- Front electric windows
- Drivers airbag
- Central locking


### Photos







## Condition Check



## Damage Photos



1: Carpets Front  
Torn  
Over 10mm



2: Sill os  
Scratched  
Over 25mm Not Thru Paint



3: Bonnet  
Dented  
With Paint Damage



4: Bumper Front  
Chipped  
Multiple Chips



5: Wing of  
Dented  
With Paint Damage



6: Roof  
Rusted  
Over 5mm



7: Tailgate  
Dented  
With Paint Damage



8: Bumper Rear Moulding  
Scuffed (Unpainted)  
Up To 100mm



9: Fog Lamp nsr  
Broken  
Replace



10: Qtr Panel nsr  
Dented  
With Paint Damage



11: Door nsr  
Dented  
2 Or Less UpTo 10mm



12: Door nsf  
Chipped  
Edge Chip



13: Door Mirror Assy osf  
Scuffed (Unpainted)  
Over 100mm

## Interior



<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	OK	<b>Odour</b>	No
Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	Fault	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK