

VEHICLE INSPECTION REPORT

KHF029

11.00-20 Tyres (5 of)

Inspection

Vehicle

VAT	Margin
V5	N/A

Details

Location	Onsite Customer Auction	Mileage	Not Showing	VIN
Reg. date		Fuel Type		
Year		Colour		

Tyres

NSF


NSR

OSF

OSR

Spare

Photos





Commercial Vehicle Auctions Limited