

VEHICLE INSPECTION REPORT

PK71JFX

Fiat Doblo Work Up 1.6 MULTIJET 16V

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 08/12/2021

VIN ZFA26300006V46021

CAP Below £5,475.00

Year 2021

Body Style Dropside L2

Gearbox MANUAL

Mileage 76,699 Miles
Warranted

MOT Due 28/04/2026

Gears 5

Fuel Type DIESEL

CAP Clean £7,150.00

Colour WHITE

CAP Average £6,525.00

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim
- Drivers airbag
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: B Post ns
Poor Previous Repair
Rippled UpTo 30%



8: B Post os
Poor Previous Repair
Rippled UpTo 30%



9: Seat Base Cover osf
Soiled
Heavy



10: Carpets Front
Holed
Over 3mm



11: Seat Base Cover nsf
Soiled
Heavy



12: Fascia Panel
Holed
Over 3mm

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		