

VEHICLE INSPECTION REPORT

MX22UJH

Ford Transit Custom 340 2.0 EcoBlue 130PS Leader

Non Runner
Inspection

Serious Damage?	No	Vehicle	
		VAT	Plus VAT
		V5	To Follow
		Cap Id	44507
		Cap Code	FOTU2034LLHDTM2 1 L

Details

Location	Livingston	GVW	3400kg	CAP Clean	£10,800.00
Reg. date	10/05/2022	Colour	WHITE	CAP Average	£9,800.00
Year	2022	VIN	WF0YXXTTGYMK10264	CAP Below	£8,250.00
Mileage	30,559 Miles Warranted	Body Style	Panel Van L2	Gearbox	MANUAL
Fuel Type	Diesel	MOT Due	11/05/2027	Gears	6

NON-RUNNER, DOES NOT START OR DRIVE, MAY OR MAY NOT APPEAR ON VCAR SIDE LOAD DOOR, ROOF RACK, LEATHER, AD-BLUE.

Tyres

NSF

NSR

OSF

OSR



Spare

Features


- Front parking sensor
- Rear parking sensor
- Radio/CD
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30% Of Panel

2: Headlamps
Missing
Replace



3: Bumper Front Moulding
Broken
Replace

4: Wing nsf
Missing
Replace



5: Door Mirror Assy nsf
Broken
Replace

6: Door nsf
Dented
With Paint Damage



7: Door nsr
Dented
With Paint Damage

8: Door Moulding nsf
Missing
Replace



9: Tailgate
Dented
With Paint Damage

10: Bumper Rear Moulding
Broken
Replace



11: Other
N/A
N/A

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs		Fault	Gearbox 1st and Reverse Test	Fault
Brakes		Fault	Clutch Slip Test from Static	Fault
Turbo Boosting		Fault	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake		Fault	No Excessive Smoking	Fault
EML light illuminated		Fault	Oil warning light illuminated	Fault
Airbag light illuminated		Fault	DPF light illuminated	Fault
ABS light illuminated		Fault	Service indicator light illuminated	Fault

Windows

OK

Radio

OK

Steering

Fault