

# VEHICLE INSPECTION REPORT

**FM21HSJ**

## Iveco Daily 35-140

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 11/08/2021

Year 2021

Mileage 174,214 Miles  
Warranted

Fuel Type Diesel

Colour SILVER

VIN ZCFC35A40D684674

Body Style Dropside

MOT Due 02/10/2025

CAP Clean £6,825.00

CAP Average £6,150.00

CAP Below £5,200.00

Gearbox MANUAL

\*WARNING LIGHT ON DASH\* 3750WB, AD-BLUE

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Wing nsf  
Dented  
With Paint Damage






3: Door nsf  
Scratched  
Over 25mm Thru Paint



4: Door osf  
Dented  
With Paint Damage



5: Wing osf  
Dented  
With Paint Damage



6: Dash Warning Lights  
Displayed  
No Action



7:

Interior

Carpet Condition OK  
Seat Condition OK

Upholstery Condition OK  
Odour -

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		