

VEHICLE INSPECTION REPORT

YK64LXN

MERCEDES ATEGO

Inspection

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Bedford	Colour	WHITE	Gearbox	MANUAL
Reg. date	17/09/2014	VIN	WDF9505092B979144	Axle Combi	4x2
Year	2014	Body Style	Box Van	Rear Suspension	Steel
Mileage	294,887 Km Warranted	Service history	Yes	Rear Doors	Barn
Fuel Type	DIESEL	MOT Due	30/09/2027	Tail Lift	Cantilever
GVW	18000kg	Cab Type	SLEEPER CAB		

WARNING LIGHT ON DASH

Tyres

NSF
NSR
OSF
OSR
Spare

Photos



