

VEHICLE INSPECTION REPORT

NK73YJY

Mercedes-Benz Sprinter 315 CDI Progressive

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	49244
		Cap Code	MESP2053PGHDTM2 5 L

Details

Location	Livingston	GVW	3500kg	CAP Clean	£18,550.00
Reg. date	21/11/2023	Colour	WHITE	CAP Average	£17,200.00
Year	2023	VIN	W1V3HCFZXP600082	CAP Below	£14,800.00
Mileage	76,683 Miles Warranted	Body Style	Panel Van L3	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	20/11/2026	Gears	6

SIDE LOAD DOOR, SPARE WHEEL, AD-BLUE.

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Radio/CD
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Roof
Dented
Over 30mm



3: Door nsr
Dented
With Paint Damage

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK
Windows	OK		Radio	OK
			Steering	OK