

VEHICLE INSPECTION REPORT

SJ16XLZ

Daf LF 220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date	25/05/2016	VIN	XLRAEL3700L449068	Cab Type	DAY CAB
Year	2016	Body Style	Gully Emptier	Gearbox	auto
Mileage	126,121 Km Warranted	Keys	1	Doors	2
Fuel Type	Diesel	Service history	Part	Steering Combi	Steer
Colour	YELLOW	Service documents	Printout	Rear Suspension	Steel

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Sill os
Rusted
Over 5mm



3: Door Moulding osf
Scuffed (Unpainted)
Over 100mm



4: Bonnet
Chipped
1 To 5



5: Bumper Front
Dented
With Paint Damage



6: Wing osf
Scratched
Over 25mm Thru Paint



7: Door osf
Dented
Between 10mm + 30mm



8: Qtr Panel osr
Rusted
Over 5mm



9: Tailgate
Rusted
Over 5mm



10: Qtr Panel nsf
Rusted
Over 5mm



11: Door nsf
Rusted
Over 5mm



12: Door Moulding nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	

Windows

OK

Radio

OK

Steering

OK