

VEHICLE INSPECTION REPORT

PJ73XNO

Daf LF 260

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Doncaster

Reg. date 11/01/2024

Year 2024

Mileage 25,963 Km Not Warranted

Fuel Type DIESEL

GVW 18000kg

Colour WHITE

VIN XLRAEL3700L519344

Body Style Skiploader

MOT Due 30/09/2027

Cab Type DAY CAB

Gearbox MANUAL

Axle Combi 4x2

Rear Suspension Steel

AJK BODY SLK12-T-V1-381 (YEAR 2022)

Tyres






NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Radio/CD
- Cloth seat trim
- Cruise control
- Air conditioning
- Park assist camera
- Front electric windows
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm

4: Door osf
Scratched
Over 25mm Thru Paint



5: Door osf
Scratched
Over 25mm Thru Paint

6: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		