

VEHICLE INSPECTION REPORT

NK73YJV

Mercedes-Benz Sprinter 315 CDI Progressive

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	49244
		Cap Code	MESP2053PGHDTM2 5 L

Details

Location	Livingston	GVW	3500kg	CAP Clean	£17,300.00
Reg. date	21/11/2023	Colour	WHITE	CAP Average	£16,000.00
Year	2023	VIN	W1V3HCFZ7PP597641	CAP Below	£13,750.00
Mileage	89,717 Miles Warranted	Body Style	Panel Van L3	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	20/11/2026	Gears	6

SIDE LOAD DOOR, AD-BLUE.

Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Radio/CD
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Bonnet
Chipped
Multiple Chips



3: Screen Front
Cracked
Replace



4: Tailgate
Dented
With Paint Damage



5: Qtr Panel nsr
Cracked
Replace



6: Qtr Panel osr
Dented
With Paint Damage

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		