

VEHICLE INSPECTION REPORT

YK18GJP

Ford Transit 350 2.0 TDCi 130PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	37868
		Cap Code	FOTR2035R36DTM2 4 L

Details

Location	Livingston	Colour	WHITE	CAP Clean	£3,625.00
Reg. date	06/07/2018	VIN	WF0XXXTTGXJS54598	CAP Average	£3,075.00
Year	2018	Body Style	Panel Van L2	CAP Below	£2,325.00
Mileage	127,599 Miles Warranted	Service history	Part	Gearbox	MANUAL
Fuel Type	DIESEL	Service documents	Printout	Gears	6
GVW	3500kg	MOT Due	17/07/2027		

COLLECTED AS NON-RUNNER, ENGINE BLOCK CRACKED, REQUIRES NEW ENGINE SIDE LOAD DOOR, TOW BAR, REAR VIEW CAMERA, HEATED WINDSCREEN.

Tyres



NSF
NSR
OSF
OSR
Spare

Features


- Front parking sensor
- Rear parking sensor
- Radio/CD
- Air conditioning

Photos





Condition Check



Damage Photos



1: Bonnet
Rusted
Over 5mm



2: Bonnet
Chipped
Multiple Chips



3: Panel Rear
Scratched
Over 25mm Thru Paint

4: Roof
Rusted
Over 5mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Turbo Boosting		OK		Gearbox Static Gear Selection (engine running)		OK	
Parking Brake		OK		No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	