

VEHICLE INSPECTION REPORT

YK64KFD

Daf LF 55.250

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Doncaster

GVW 18000kg

Cab Type DAY CAB

Reg. date 24/09/2014

Colour WHITE

Gearbox AUTOMATIC

Year 2014

VIN XLRAE55GF0L430579

Axle Combi 4x2

Mileage Not Showing

Body Style Tanker

Rear Suspension Steel

Fuel Type DIESEL

Service history None

***NON-RUNNER - DOES NOT TURN OVER, PARTS STRIPPED* YEAR (2014) WHALE BODY, 15PSI MAX WORKING PRESSURE, MOT SHOWS 272,484 KM 19/12/2024**


Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Cruise control
- Park assist camera
- Auxiliary input socket
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check




Damage Photos




1: Bonnet
Cracked
Replace




2: Headlamp os
Missing
Replace



3: Panel Front
Missing
Replace



4: Bumper Front
Dented
With Paint Damage



5: Bumper Front Grill
Missing
Replace



6: Headlamp ns
Missing
Replace



7: Panel Front
Missing
Replace



8: Bumper Front
Dented
With Paint Damage



9: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



10: Door nsf
Scratched
Over 25mm Thru Paint



11: Wing nsf
Scratched
Over 25mm Thru Paint



12: Wing osf
Scratched
Over 25mm Thru Paint



13: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	Fault		