

VEHICLE INSPECTION REPORT

C379936

GRAY & ADAMS BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Bedford	Colour	WHITE	Axle Combi	Tri
Reg. date	01/01/2014	VIN	SMXDA3BFSED034089	Rear Suspension	Air
Year	2014	Body Style	Trailer	Rear Doors	Roller
Mileage	Not Showing	MOT Due	30/11/2026		
Fuel Type		Brakes	Drum		

BPW AXLES, FERRY LASHING RINGS, RAISE & LOWER VALVE

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



