

VEHICLE INSPECTION REPORT

VO20SNK

Vauxhall Vivaro 3100 2.0d 120PS Edition

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply
		Cap Id	44146
		Cap Code	VAVI20212DZDTM2 3 L

Details

Location	Doncaster	GVW	2940kg	CAP Clean	£4,200.00
Reg. date	25/08/2020	Colour	WHITE	CAP Average	£3,675.00
Year	2020	VIN	VXEVFHKKLZ058577	CAP Below	£2,975.00
Mileage	122,909 Miles Warranted	Body Style	Crew Van L2	Gearbox	MANUAL
Fuel Type	DIESEL	Service history	None	Gears	6


TWIN SIDE LOAD DOORS, AD-BLUE, E/MIRRORS

Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Scratched
Over 25mm Thru Paint



3: Qtr Panel nsr
Chipped
Multiple Chips



4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



6: Door osr
Dented
With Paint Damage



7: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



8: Qtr Panel osr
Scratched
Over 25mm Thru Paint



9: Qtr Panel osr
Chipped
Multiple Chips



10: Sill os
Dented
With Paint Damage



11: Sill os
Dented
With Paint Damage



12: Wing osf
Dented
With Paint Damage



13: Screen Front
Cracked
Replace



14: Fascia Panel
Broken
Replace



15: Seat Base Cover nsf
Torn
Over 3mm



16: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		OK		Upholstery Condition		Poor	
Seat Condition		Poor		Odour		No	
Engine Runs		OK		No Excessive Smoking		OK	
EML light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		Fault	