

VEHICLE INSPECTION REPORT

WX70KKP

Fiat Ducato 2.3 Multijet 140

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	44846
Cap Code	FIDU233MM4HDTM2 5 L

Details

Location	Doncaster	GVW	3500kg	CAP Clean	£9,175.00
Reg. date	27/01/2021	Colour	WHITE	CAP Average	£8,200.00
Year	2021	VIN	ZFA25000002R33041	CAP Below	£6,725.00
Mileage	31,547 Miles Warranted	Body Style	Panel Van MWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	02/11/2026	Gears	6

RACKING IN REAR, AD-BLUE, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Door Mirror Assy nsf
Broken
Replace



4: Door nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Chipped
Multiple Chips



7: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



8: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		