

VEHICLE INSPECTION REPORT

SJ18YDK

VAUXHALL MOVANO F3500 2.3 CDTI 130ps

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow
		Cap Id	38271
		Cap Code	VAMO233330ZDTM2 2 L

Details			
Location	Livingston	GVW	3500kg
Reg. date	17/05/2018	Colour	WHITE
Year	2018	VIN	W0VMRY602JB149230
Mileage	73,613 Miles Warranted	Body Style	Panel Van L3
Fuel Type	DIESEL	MOT Due	14/04/2027
		CAP Clean	£5,775.00
		CAP Average	£4,900.00
		CAP Below	£3,725.00
		Gearbox	MANUAL
		Gears	6


SIDE LOAD DOOR, TOW BAR, ROOF RACK, E/MIRRORS, AD-BLUE, OUTSTANDING RECALL.

Tyres
NSF
NSR
OSF
OSR
Spare

Features

- Rear parking sensor
- Radio/CD
- Front electric windows
- Central locking

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Chipped
Multiple Chips



3: Sill os
Scratched
Over 25mm Thru Paint



4: Qtr Panel Moulding os
Broken
Replace



5: Qtr Panel osr
Dented
With Paint Damage



6: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel osr
Dented
With Paint Damage



8: Panel Front
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Turbo Boosting		OK		Gearbox Static Gear Selection (engine running)		OK	
Parking Brake		OK		No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	