

VEHICLE INSPECTION REPORT

4356549

Scania R143.420 V8 Topline Streamline

**Non Runner
Inspection**

Vehicle

VAT	Margin
V5	Buyer To Apply

Details

Location	Onsite Customer Auction	Fuel Type	Diesel	Gearbox	Manual
Reg. date		Colour		Axle Combi	4x2
Year		VIN	XLERA4X2A04356549		
Mileage	884,432 Km Not Warranted	Body Style	Tractor Unit		

Non-Runner - Was Running When Parked Up 2 Years Ago Left Hand Drive, Sliding 5th Wheel

Tyres

NSF
NSR
OSF
OSR
Spare

Photos





