

VEHICLE INSPECTION REPORT

HX67VMP

Daf CF 330

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location Doncaster

Reg. date 01/09/2017

Year 2017

Mileage 294,789 Km Not Warranted

Fuel Type DIESEL

GVW 26000kg

Colour WHITE

VIN XLRASM4100G160676

Body Style Dropside & Crane

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Rear Suspension Air

REAR LIFT, HIAB X-HIDUO REMOTE CRANE 138

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3




OSO4


Features

- Bluetooth connection
- Digital radio
- Cloth seat trim
- Cruise control
- Air conditioning
- Navigation system
- Front electric windows
- Auxiliary input socket
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Edge Chip



2: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Door Moulding of
Scuffed (Unpainted)
Over 100mm



5: Door of
Chipped
Multiple Chips



6: Panel Front
Chipped
Edge Chip



7: Door of
Chipped
Edge Chip



8: Door of
Chipped
Edge Chip



9: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



10: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



11: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



12: Moulding nsf Wing
Broken
Replace



13: Moulding nsf Wing
Scuffed (Unpainted)
Over 100mm



14: Other
N/A
N/A



15: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	Fault	Radio	OK
Sat nav	OK	Steering	OK