



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DK68WFG

Man TGS 26.360

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Cap Code 999900

Details

Location	Bedford	GVW	26000kg	Cab Type	DAY CAB
Reg. date	10/10/2018	Colour	BLUE	Gearbox	AUTOMATIC
Year	2018	VIN	WMA18SZZ6JM797300	Axle Combi	6x2
Mileage	143,113 Km Warranted	Body Style	Dropside & Crane	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	31/05/2027		

SERVICE SCHEDULE LIST AVAILABLE, HMF 1420K REMOTE CRANE (YEAR 2018), REAR LIFT, SURROUND CAMERA SYSTEM


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Wing and
Chipped
Multiple Chips



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: A Post ns
Scratched
Over 25mm Not Thru Paint



7: Wing Front Arch Extension ns
Scuffed (Unpainted)
Over 100mm



8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsf
Scratched
UpTo 25mm Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Door osf
Scratched
Over 25mm Thru Paint



13: Wing Front Arch Extension os
Scuffed (Unpainted)
Over 100mm




14: A Post os
Scratched
Over 25mm Not Thru Paint



15: Door osr
Chipped
Edge Chip



16: Qtr Panel osr
Scratched
Up To 25mm Thru Paint



17: Seat Base Cover osf
Holed
Over 3mm



18: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average	Odour	Average
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK