

VEHICLE INSPECTION REPORT

ST13RHK

Ford Transit Connect Low Roof Van TDCi 75ps

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	16534
Cap Code	FOTC180S7 VDTM2 1 L

Details

Location	Livingston	GVW	2040kg	CAP Clean	£900.00
Reg. date	20/08/2013	Colour	YELLOW	CAP Average	£700.00
Year	2013	VIN	WF0TXXTPTDR72964	CAP Below	£470.00
Mileage	121,044 Miles Warranted	Body Style	Panel Van SWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	Expired	Gears	5

SIDE LOAD DOOR.

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Radio/CD
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Panel Front
Dented
With Paint Damage



3: Sill os
Rusted
Over 5mm



4: Qtr Panel osr
Rusted
Over 5mm



5: Bumper Rear
Rusted
Over 5mm



6: Door nsr
Rusted
Over 5mm



7: Sill ns
Rusted
Holed

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Turbo Boosting		OK		Gearbox Static Gear Selection (engine running)		OK	
Parking Brake		OK		No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	