

VEHICLE INSPECTION REPORT

H116NFS

FODEN S106

Inspection

Vehicle

VAT	Margin
V5	Buyer To Apply
Cap Code	999900

Details

Location	Onsite Customer Auction	Mileage	412 Km Not Warranted	VIN	404397
Reg. date	15/02/1991	Fuel Type	PETROL/GAS	Body Style	Recovery
Year	1991	Colour	YELLOW	Axle Combi	6x6

Power Steering U/S Heavy Duty Telescopic Underlift Equipment, Winch, Rolls Royce TX Engine, 8Sp. Gearbox, All Wheel Drive

Tyres

NSF

NSR

OSF

OSR

Spare

Photos



