

VEHICLE INSPECTION REPORT

AY16MFO

DAF CF 220

Inspection

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Bedford	Colour	SILVER	Axle Combi	4x2
Reg. date	01/03/2016	VIN	XLRAEM3700G092117	Rear Suspension	Air
Year	2016	Body Style	Curtainside	Rear Doors	Barn
Mileage	804,625 Km Not Warranted	MOT Due	28/02/2027	Tail Lift	Tuckaway
Fuel Type	DIESEL	Cab Type	SLEEPER CAB		
GVW	18000kg	Gearbox	MANUAL		

CRACK IN WINDSCREEN, WARNING LIGHT ON DASH

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Park assist camera

Photos





