

VEHICLE INSPECTION REPORT

B430058

VOLVO F12

Non Runner

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Onsite Customer Auction	Fuel Type	Diesel	Gearbox	Manual
Reg. date		Colour		Axle Combi	4x2
Year		VIN			
Mileage	479,419 Km Not Warranted	Body Style	Tractor Unit		

Non-Runner - Was Running When Parked 2 Years Ago Left Hand Drive, A/C

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





