

VEHICLE INSPECTION REPORT

K101HSA

FODEN 4300

Inspection

Vehicle

VAT	Margin
V5	Buyer To Apply
Cap Code	999900

Details

Location	Onsite Customer Auction	Fuel Type	DIESEL	Gearbox	Manual
Reg. date	01/01/1993	Colour	BLUE	Axle Combi	8x4
Year	1993	VIN	405491		
Mileage	22,239 Km Not Warranted	Body Style	Tipper		

Caterpillar Engine, Harsh Underfloor Tipping Gear, Alloy Tipping body With Fold down Sides, Alloy Wheels

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





