

VEHICLE INSPECTION REPORT

NU67WTP

Iveco Eurocargo 180-250

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply
		Cap Code	999900

Details

Location	Livingston	Colour	WHITE	Axle Combi	4x2
Reg. date	24/11/2017	VIN	ZCFA71TJ502667444	Rear Suspension	Steel
Year	2017	Body Style	Curtainside	Rear Doors	Barn
Mileage	179,893 Km Not Warranted	MOT Due	31/07/2027	Tail Lift	Tuckaway
Fuel Type	Diesel	Cab Type	SLEEPER CAB		
GVW	18000kg	Gearbox	Manual		

TAIL LIFT REQUIRES ATTENTION


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Radio/CD

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Qtr Panel nsr
Hole
Over 10mm



3: Other
N/A
N/A

4: Qtr Panel osr
Hole
Over 10mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake		OK	No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK