

VEHICLE INSPECTION REPORT

WU67VMT

Ford Transit 310 2.0 TDCi 130ps

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply
		Cap Code	FOTU201S3 VDTM2 L

Details

Location	Doncaster	Fuel Type	DIESEL	Body Style	Panel Van L1
Reg. date	01/09/2017	GVW	3140kg	MOT Due	Expired
Year	2017	Colour	WHITE	Gearbox	MANUAL
Mileage	98,227 Miles Warranted	VIN	WF0YXXTTGYHA23775	Gears	6

240V 1000W MODUL SYSTEM POWER INVERTER

Tyres

NSF

NSR

OSF


OSR



Spare

Features

- Bluetooth connection
- Air conditioning
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Door osf
Chipped
Edge Chip



4: Sill os
Scratched
Rusted



5: Sill ns
Chipped
Edge Chip



6: Sill ns
Chipped
Edge Chip



7: Sill ns
Rusted
Over 5mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK