

VEHICLE INSPECTION REPORT

GH16MJE

Mercedes-Benz Arocs 2648

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Code	999900

Details

Location	Bedford	GVW	38000kg	Cab Type	CLASSICSPACE CAB
Reg. date	24/06/2016	Colour	WHITE	Gearbox	AUTOMATIC
Year	2016	VIN	WDB96440320046729	Axle Combi	4x2
Mileage	333,372 Km Not Warranted	Body Style	Tractor Unit	Rear Suspension	Air
Fuel Type	DIESEL	MOT Due	31/03/2027		

INTERMITTENT WARNING LIGHTS ON DASH

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Not Thru Paint



2: Fog Lamp Surround os
Scratched (Painted)
Over 25mm Thru Paint



3: Bumper Front
Dented
With Paint Damage



4: Screen Front
Chipped
Over 10mm



5: Bonnet
Scratched
UpTo 25mm Thru Paint



6: Bumper Front
Dented
With Paint Damage



7: Fog Lamp Surrounds
Scratched (Painted)
Over 25mm Thru Paint



8: Bumper Front
Insecure
Action Required



9: Wing nsf
Scratched
Over 25mm Not Thru Paint



10: Door Mirror Assy nsf
Broken
Replace



11: Door Mirror Glass ns
Missing
Replace



12: Wing Front Arch Extension ns
Broken
Replace



13: Qtr Panel Arch Extension ns
Missing
Replace



14: Lamp nsr
Missing
Replace



15: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



16: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



17: Door osf
Chipped
Edge Chip



18: Door Pad osf
Broken
Replace

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Parking Brake	OK			Gearbox Static Gear Selection (engine running)	OK		
				No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	OK		
ABS light illuminated	OK			Service indicator light illuminated	OK		