

VEHICLE INSPECTION REPORT

MK16HHO

Vauxhall Combo 2300 1.6 CDTI 16V 105pS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow
		Cap Id	24261
		Cap Code	VACO16L235VDTM2 3 L

Details

Location	Doncaster	Colour	SILVER	CAP Average	£840.00
Reg. date	29/08/2016	VIN	W0L6WYD1BG9595041	CAP Below	£610.00
Year	2016	Body Style	Panel Van L2	Gearbox	MANUAL
Mileage	113,769 Miles Warranted	Service history	None	Gears	5
Fuel Type	DIESEL	MOT Due	24/11/2026		
GVW	2370kg	CAP Clean	£1,025.00		

COLLECTED AS A NON-RUNNER, POOR BRAKES, ENGINE MISFIRE TWIN SIDE LOAD DOORS

Tyres

NSF

NSR

OSF

OSR






Spare

Features

- Bluetooth connection
- Front electric windows
- Central locking
- Rear parking sensor
- Metallic Paint
- Cloth seat trim
- Digital radio
- Drivers airbag
- Air conditioning
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Dented
Over 30mm



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Wing osf
Scratched
Over 25mm Thru Paint



6: Screen Front
Cracked
Replace



7: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	Fault	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		