

VEHICLE INSPECTION REPORT

MXZ9774

NEOPLAN TOURLINER

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Cap Code 999900

Details

Location	Doncaster	GVW	24900kg	MOT Due	31/07/2027
Reg. date	05/04/2019	Colour	WHITE	Cab Type	CREW CAB
Year	2019	VIN	WAGP20ZZ7JT028761	Gearbox	AUTOMATIC
Mileage	334,577 Km Not Warranted	Body Style	Coach	Axle Combi	6x2
Fuel Type	DIESEL	Service history	None	Rear Suspension	Air

5% BUYERS FEE 54 SEATS PLUS CREW & DRIVER, TOILET, TV SYSTEM, OVERHEAD STOWAGE, CLOTH RECLINING SEATS WITH FOOT RESTS, 3PT SEATBELTS, FULL WIDTH UNDERBODY STORAGE, PA SYSTEM

Tyres





NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Digital radio
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



4: Door Moulding nsf
Broken
Replace



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Dented
With Paint Damage



7: Panel Rear
Scratched
Over 25mm Thru Paint



8: Panel Rear
Cracked
Replace



9: Bumper Rear
Poor Previous Repair
Rippled Over 30%



10: Panel Rear
Scratched
Over 25mm Thru Paint



11: Panel Front
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		