

VEHICLE INSPECTION REPORT

GV73XTH

ISUZU D-MAX 1.9 V-CROSS

Inspection

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	51524
Cap Code	ISDM19VCRO7DTA4 2 L

Details

Location	Bedford	Colour	ORANGE	CAP Below	£20,400.00
Reg. date	29/12/2023	VIN	MPATFS87JPT028759	Gearbox	AUTOMATIC
Year	2023	Body Style	Pickup Double Cab	Gears	6
Mileage	26,890 Miles Not Warranted	MOT Due	28/12/2026	Axle Combi	4x4
Fuel Type	DIESEL	CAP Clean	£25,500.00		
GVW	3100kg	CAP Average	£23,600.00		

AD BLUE, HEATED SEATS, TOW BAR, E/MIRRORS, ALLOY WHEELS, NEW KEEPER SLIP IN OFFICE

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Front parking sensor
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows
- Rear electric windows
- Leather seat trim