

VEHICLE INSPECTION REPORT

PG66UEA

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Doncaster

Reg. date 21/02/2017

Year 2017

Mileage 1,144,811 Km
Warranted

Fuel Type DIESEL

GVW 44000kg

Colour RED

VIN XLRTGM4100G147122

Body Style Tractor Unit

Service history Yes

Service documents Printout

Last service date 11/04/2026

MOT Due 31/03/2027

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3


OSO4

Features

- Bluetooth connection
- Radio/CD
- Cloth seat trim
- Cruise control
- Air conditioning
- Auxiliary input socket
- Front electric windows
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Missing
Replace



3: Panel Front
Cracked
Replace



4: Panel Front
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



7: Door osf
Scratched
Over 25mm Not Thru Paint



8: Screen Front
Chipped
Over 10mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		