

VEHICLE INSPECTION REPORT

SD64DWK

Ford Transit 310 2.2 TDCi 125PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present
		Cap Id	30568
		Cap Code	FOTR221L2 6DTM2 4 L

Details

Location	Livingston	VIN	WF0XXXTTGXER11490	CAP Clean	£3,250.00
Reg. date	10/12/2014	Body Style	Panel Van L2	CAP Average	£2,600.00
Year	2014	Service history	Full	CAP Below	£1,750.00
Mileage	92,889 Miles Warranted	Service documents	Printout	Gearbox	MANUAL
Fuel Type	DIESEL	Last service date	30/06/2026	Gears	6
GVW	3100kg	Last service miles	90,964		
Colour	WHITE	MOT Due	19/12/2026		

SIDE LOAD DOOR, TOW BAR, REAR VIEW CAMERA.

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Rear parking sensor
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Qtr Panel osr
Chipped
Multiple Chips



3: Tailgate
Dented
With Paint Damage



4: Tailgate
Dented
With Paint Damage



5: Qtr Panel nsr
Dented
With Paint Damage



6: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		No	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Turbo Boosting		OK		Gearbox Static Gear Selection (engine running)		OK	
Parking Brake		OK		No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	