

VEHICLE INSPECTION REPORT

LR73ZYE

Maxus Deliver 9 2.0 D20 150PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply
		Cap Id	55901
		Cap Code	MXD920LW509DTM2 L

Details

Location	Livingston	GVW	3500kg	CAP Clean	£11,500.00
Reg. date	12/10/2023	Colour	WHITE	CAP Average	£10,650.00
Year	2023	VIN	LSH14J7C8PA822466	CAP Below	£9,175.00
Mileage	33,092 Miles Warranted	Body Style	Panel Van LWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	11/10/2026	Gears	6


SIDE LOAD DOOR, E/MIRRORS, AD-BLUE.


Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Carpets Front
Torn
Over 10mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Chipped
Multiple Chips



4: Qtr Panel osr
Dented
With Paint Damage



5: Qtr Panel osr
Dented
Over 30mm



6: Badgedecal Rear
Missing
Replace



7: Qtr Panel nsr
Dented
Over 30mm



8: Sill ns
Dented
Over 30mm



9: Sill ns
Rusted
Over 5mm



10: Door nsf
Dented
With Paint Damage

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Poor		Average	
Average		No	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK