



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PF70EAO

Fiat Ducato Maxi 35 2.3 MULTIJET 140PS

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	44906
Cap Code	FIDU233MM4BDTM2 5 L

Details

Location	Doncaster	Colour	MULTI-COLOURED	CAP Average	£4,150.00
Reg. date	27/01/2021	VIN	ZFA25000002P02642	CAP Below	£3,400.00
Year	2021	Body Style	Dropside MWB	Gearbox	MANUAL
Mileage	97,179 Miles Warranted	Service history	None	Gears	6
Fuel Type	DIESEL	MOT Due	09/02/2027		
GVW	3500kg	CAP Clean	£4,625.00		

AD-BLUE, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR




Spare

Features

- Bluetooth connection
- Front electric windows
- Park assist camera
- Drivers airbag
- Digital radio
- Central locking
- Air conditioning
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Missing
Replace



2: Bonnet
Dented
With Paint Damage



3: Bonnet
Chipped
Multiple Chips



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm




5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Wing nsf
Chipped
Multiple Chips



7: Door Moulding nsf
Broken
Replace



8: Door Mirror Assy nsf
Broken
Replace



9: Fuel Flap
Scratched
Over 25mm Thru Paint



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel osr
Dented
Over 30mm



12: B Post os
Chipped
Multiple Chips



13: Door Mirror Assy osf
Broken
Replace



14: Wing osf
Scratched
Over 25mm Thru Paint



15: Wing osf
Scratched
Over 25mm Thru Paint



16: Carpets Front
Holed
Over 3mm



17: Seat Base Cover osf
Holed
Over 3mm



18: Fascia Panel
Missing
Replace



19: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		Poor	Upholstery Condition		Poor
Seat Condition		Poor	Odour		No
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			