

VEHICLE INSPECTION REPORT

PE17HNL

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Bedford

Reg. date 06/03/2017

Year 2017

Mileage 1,197,641 Km
Warranted

Fuel Type DIESEL

GVW 44000kg

Colour RED

VIN XLRTGM4100G149148

Body Style Tractor Unit

Service history Yes

MOT Due 30/11/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

WARNING LIGHTS ON DASH SURROUND CAMERA SYSTEM

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4


Spare NSO1 NSO2 NSO3 NSO4



OSO1 OSO2 OSO3 OSO4


Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Bumper Front
Chipped
Multiple Chips



2: Fog Lamp Surround os
Broken
Replace



3: Wing osf
Chipped
Multiple Chips



4: Front TowEye Cvr
Missing
Replace



5: Bonnet
Chipped
Multiple Chips



6: Screen Front
Chipped
UpTo 10mm



7: Bumper Front
Dented
With Paint Damage



8: Fog Lamp Surround ns
Scratched (Painted)
UpTo 25mm Not Thru Paint



9: Wing nsf
Chipped
Multiple Chips



10: Door Mirror Assy nsf
Broken
Replace



11: Wing Front Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm



12: Qtr Panel Arch Extension ns
Broken
Replace



13: Qtr Panel Arch Extension os
Broken
Replace



14: Wing Front Arch Extension os
Broken
Replace



15: Door osf
Dented
With Paint Damage



16: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



17: Qtr Panel osr
Chipped
Multiple Chips



18: Carpets Front
Holed
Over 3mm



19: Switches And Controls
Broken
Replace



20: Steering Wheel
Damaged
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)		OK
			No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		Fault
ABS light illuminated		OK	Service indicator light illuminated		OK