

# VEHICLE INSPECTION REPORT

**YY16MVE**

## Daf CF 310

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

|           |                      |            |                   |                 |                 |
|-----------|----------------------|------------|-------------------|-----------------|-----------------|
| Reg. date | 25/07/2016           | VIN        | XLRASM4700G099676 | Axle Combi      | 6x2             |
| Year      | 2016                 | Body Style | Dropside & Crane  | Steering Combi  | Rear-Lift Steer |
| Mileage   | 253,983 Km Warranted | MOT Due    | Expired           | Rear Suspension | Air             |
| Fuel Type | Diesel               | Cab Type   | DAY CAB           |                 |                 |
| Colour    | GREEN                | Gearbox    | AUTOMATIC         |                 |                 |

\*WARNING LIGHT ON DASH\* ATLAS 129.3V-A12 REMOTE CRANE (YEAR 2016), SURROUND CAMERA SYSTEM

### Tyres

|       |      |      |      |      |
|-------|------|------|------|------|
| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |

## Features

- Park assist camera
- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Bumper Front  
Scratched  
Over 100mm Thru Paint



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front  
 Scratched  
 Over 100mm Thru Paint

4: Door nsf  
 Dented  
 Over 30mm



5: Door osf  
 Dented  
 With Paint Damage

Interior

|                  |    |                      |    |
|------------------|----|----------------------|----|
| Carpet Condition | -  | Upholstery Condition | -  |
| Seat Condition   | -  | Odour                | -  |
| Engine Runs      | OK | No Excessive Smoking | OK |