

VEHICLE INSPECTION REPORT

LP73YUF

Maxus Deliver 9 2.0 D20 150PS

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	63650
Cap Code	MXD920LW50BDTM2 1 L

Details

Location	Avonmouth	Fuel Type	DIESEL	Body Style	Tipper LWB
Reg. date	21/02/2024	GVW	3500kg	MOT Due	20/02/2027
Year	2024	Colour	WHITE	Gearbox	MANUAL
Mileage	44,874 Miles Not Warranted	VIN	LSFAL11A8PA088673	Gears	6

AD BLUE, TOW BAR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR




Spare

Features

- Bluetooth connection
- Auxiliary input socket
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Carpets Front
Holed
Over 3mm



2: Bonnet
Chipped
Edge Chip



3: Grille Front
Scratched (Painted)
Over 25mm Thru Paint



4: Bumper Front
Chipped
Over 5mm



5: Bumper Front
Scratched
Over 100mm Thru Paint



6: Bumper Rear
Rusted
Over 5mm



7: Tailgate
Dented
Over 30mm



8: Door osf
Chipped
Edge Chip



9: Qtr Panel Moulding os Scratched (Painted) Over 25mm Thru Paint



10: Sill os Chipped Over 5mm



11: Bumper Front Moulding Scuffed (Unpainted) Over 100mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs		Average -	
EML light illuminated		Oil warning light illuminated	
Airbag light illuminated		DPF light illuminated	
ABS light illuminated		Service indicator light illuminated	