

VEHICLE INSPECTION REPORT

C441876

CARTWRIGHT CURTAINSIDE FIXED DECK

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Livingston	Fuel Type		Brakes	Drum
Reg. date	01/01/2016	Colour	BLUE	Axle Combi	Tri
Year	2016	VIN	SMWCS39DFGA160572	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn

LOCATION UDDINGSTON, SCOTLAND, 24 HRS NOTICE REQUIRED PRIOR TO COLLECTECTION,PLATING CERTIFICATE MISSING RAISE & LOWER VALVE. GIGANT AXLES.

Tyres

NSF
NSR
OSF
OSR
Spare