

VEHICLE INSPECTION REPORT

FT72OHG

Peugeot Partner 1000 1.5 BlueHDi 100PS Professional Premium +

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	56336
Cap Code	PEPA15S0P1VDTM2 5 L

Details

Location	Livingston	GVW	2370kg	CAP Clean	£6,450.00
Reg. date	28/02/2023	Colour	WHITE	CAP Average	£5,950.00
Year	2023	VIN	VR3EFYHT2PJ551173	CAP Below	£5,125.00
Mileage	77,615 Miles Not Warranted	Body Style	Panel Van MWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	27/02/2027	Gears	6

WARNING LIGHT ON DASH OUTSTANDING RECALL, SIDE LOAD DOOR, E/MIRRORS, AD-BLUE.

Tyres

NSF

NSR

OSF



OSR


Spare

Features


- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition		Average Average	Upholstery Condition		Average No
Seat Condition			Odour		
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	Fault	