

VEHICLE INSPECTION REPORT

C480761

CARTWRIGHT CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Location	Livingston	Fuel Type		Brakes	Drum
Reg. date		Colour	BLUE	Axle Combi	Tri
Year		VIN	SMWCS39SFJA181491	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer		

LOCATION UDDINGSTON, SCOTLAND, 24HRS NOTICE REQUIRED PRIOR TO COLLECTECTION, ACCIEDNT DAMAGED, REAR DOORS MISSING, MAY OR MAY NOT APPEAR ON VCAR SAF AXLES.

Tyres

NSF
NSR
OSF
OSR
Spare