

VEHICLE INSPECTION REPORT

LS73AEA

Maxus Deliver 9 2.0 D20 150PS

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	To Follow
Cap Id	55896
Cap Code	MXD920LL50HDTM2 L

Details

Location	Avonmouth	GVW	3500kg	CAP Clean	£14,400.00
Reg. date	25/01/2024	Colour	WHITE	CAP Average	£13,600.00
Year	2024	VIN	LSH14J7C7PA154837	CAP Below	£11,950.00
Mileage	120,691 Miles Not Warranted	Body Style	Panel Van LWB	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	24/01/2027	Gears	6

WARNING LIGHTS ON DASH, COOLANT LEAK, AD BLUE, SIDE LOAD DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR




Spare


Features

- Bluetooth connection
- Rear parking sensor
- Drivers airbag
- Cruise control
- Auxiliary input socket
- Passenger airbag
- Front parking sensor
- Air conditioning
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Over 5mm



2: Bumper Front
Chipped
Multiple Chips



3: Grille Front
Scratched (Painted)
Over 25mm Not Thru Paint



4: Bonnet
Chipped
Over 5mm



5: Bumper Front
Chipped
Multiple Chips



6: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



7: Door nsf
Chipped
Edge Chip



8: Door nsr
Chipped
Over 5mm



9: Sill ns
Chipped
Over 5mm




10: Qtr Panel Arch Extension ns
Broken
Replace



11: Door osr
Chipped
Over 5mm



12: Qtr Panel osr
Rusted
Over 5mm



13: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint



14: Door osf
Chipped
Edge Chip



15: Wing osf
Scratched
Over 25mm Thru Paint



16: Roof
Rusted
Over 5mm



17: Handle Outer osf
Scratched (Painted)
Over 25mm Not Thru Paint



18: Centre Console Front
Holed
Over 3mm



19: Centre Console Front
Scuffed
Over 25mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK				
Windows	OK		Radio	OK	