

VEHICLE INSPECTION REPORT

LC63ASZ

TORO GM14

Non Runner

Inspection

Vehicle

VAT	Plus VAT
V5	Present
Cap Code	999900

Details

Location	Bedford	Mileage	Not Showing	VIN	30657313070011
Reg. date	01/02/2014	Fuel Type	DIESEL	Body Style	Ride on Mower
Year	2014	Colour	RED	Gearbox	HYDROSTATIC

NON RUNNER-DOES NOT POWER UP

Tyres

NSF
NSR
OSF
OSR
Spare