

VEHICLE INSPECTION REPORT

FN21GYA

Daf LF 230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Cap Code 999900

Details

Location Doncaster

Reg. date 23/03/2021

Year 2021

Mileage 235,012 Km Not Warranted

Fuel Type DIESEL

GVW 18000kg

Colour GREEN

VIN XLRAEL3700L499298

Body Style Skiploader

MOT Due 31/03/2027

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Steel


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Broken
Replace



2: Panel Front
Scratched
Over 25mm Thru Paint



3: Bumper Front
Dented
With Paint Damage



4: Bonnet
Chipped
Multiple Chips



5: Panel Front
Cracked
Replace



6: Bumper Front
Dented
With Paint Damage



7: Panel Front
Scratched
Over 25mm Thru Paint



8: Door Mirror Assy nsf
Broken
Replace



9: Door osf
Dented
With Paint Damage



10: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



11: Seat Base Cover nsf
Soiled
Heavy



12: Door Pad osf
Soiled
Heavy

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		Poor	
Poor		-	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		