

VEHICLE INSPECTION REPORT

YM69AFK

Ford Transit Connect 240 1.5 ECOBLUE 100PS BASE

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	Buyer To Apply
Cap Id	42555
Cap Code	FOTC154L10VDTM2 3 L

Details

Location	Bedford	GVW	2405kg	CAP Clean	£5,775.00
Reg. date	23/01/2020	Colour	WHITE	CAP Average	£5,075.00
Year	2020	VIN	WF0SXXWPGSKU69517	CAP Below	£4,075.00
Mileage	68,255 Miles Warranted	Body Style	Panel Van L2	Gearbox	MANUAL
Fuel Type	DIESEL	MOT Due	28/01/2027	Gears	6

NON RUNNER-POWERS UP DOES NOT CRANK, TIMING BELT SNAPPED SIDE LOADING DOOR, AD

BLUE

Tyres

NSF

NSR

OSF

OSR

Spare



Features

• Air conditioning


• Front electric windows

Photos





Condition Check



Damage Photos



1: Wing osf
Dented
With Paint Damage



2: Flasher Side Repeater os
Broken
Replace



3: A Post os
Scratched
UpTo 25mm Not Thru Paint



4: Screen Front
Cracked
Replace



5: Wing nsf
Dented
With Paint Damage



6: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm




7: Bumper Rear Moulding
Broken
Replace



8: Door osr
Chipped
Edge Chip



9: Door osf
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



11: Door Mirror Glass os
Broken
Replace



12: Door osf
Chipped
Edge Chip

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Engine Runs Fault